

Site	Street Address	Priority	Erosion Severity	Exposure Levels				Physical Characteristics of Area				Bank Damage				Notes	Photo	RLAA Comments
				Exposure Total	Boat Wake	Wind Waves	Flowing Water	Protection	Vegetated	Rip Rap	Near Path	Bank Ht in Feet	Undercut Rating	Undercut in Feet	Bank Collapse			
1	Arboretum S. Lot	Med	2	6	3	0	3	1	1			2	2	1.6		RL 001	City Parks property	
2	Arboretum Pavilion	High	3	6	3	0	3	1	2			3	3	3.3	Tree severely undercut	RL 002	City Parks property	
3	Arboretum N. Lot	Low	1	3	2	0	1	2	3			2	1	1		RL 003	City Parks property	
4	Behind 14075 96th	Low	1	3	2	0	1	2	3			1	1	0.7		RL 004	City Parks property	
5	Behind 14035 96th	Low	2	3	2	0	1	2	2			2	0	0		RL 005	City Parks property	
6	Just west of 14035	Low	2	3	2	0	1	1	3			4	1	0.7		RL 006	City Parks property	
7	2 lots west of 14035	Low	1	2	2	0	0	2	2			2	2	1.6	1	RL 007	City Parks property	
8	Turn north of 14035	Low	2	2	2	0	0	2	2			5	3	2.3		RL 008	City Parks property	
9	Due west of 14035	Low	2	2	2	0	0	2	2			5	2	1.3		RL 009	City Parks property	
10	Behind 14000 96th	Med	2	3	2	0	1	2	2			5	2	1.6		RL 010	City Parks property	
11	Behind 14040 96th	Low	1	3	2	0	1	2	3			4	1	1		RL 011	City Parks property	
12	13964-82 95th	Low	2	2	2	0	0	2	2			5	1	1	1	RL 012		
13	14000 95th	Low	2	2	2	0	0	2	2			5	2	1.3		RL 013		
14	14038-74 95th	Low	2	2	2	0	0	2	2			3	2	1.3		RL 014		
15	9421-33 Dallas	Low	1	3	2	0	1	2	2			2	1	0.7		RL 015		
16	9363 Dallas	Med	2	6	3	0	3	2	2			3	2	1.6	High exposure to boat wake	RL 016		
17	9351 Dallas	Med	2	6	3	0	3	2	2			3	3	3.9		RL 017		
18	14123 93rd	Low	1	6	3	0	3	2	2			2	1	1		RL 018		
19	S. side 93rd bridge	Med	2	6	3	0	3	2	2			3	2	1.6		RL 019	City Parks property	
20	100' west of #19	Med	1	6	3	0	3	1	1			5	1	0.3	1	Minor slumping into creek	City Parks property	
21	14000 92nd PI	High	2	6	3	0	3	2	2			5	2	1.3	2	Bank collapse imminent	RL 021	
22	14030 92nd PI	High	2	6	3	0	3	2	2			5	3	3.3	1	Severe undercut - unstable	RL 022	
23	14060-90 92nd PI	Med	1	6	3	0	3	2	2			5	1	1		High Exposure - boat wake	RL 023	
24	14100 92nd PI	Med	2	6	3	0	3	2	2			3	2	1.6		High Exposure - boat wake	RL 024	
25	TBHA Marina (NW)	Low	1	3	2	0	1	1	1			2	1	1.3		RL 025		
26	Behind 14101 92nd PI	Low	1	4	2	1	1	2	3			3	1	0.7		RL 026	City Parks property	
27	9081-9101 Chesshire	Low	1	5	2	3	0	2	2			2	1	1		RL 027	City Parks property	
28	Behind 9021 Chesshire	Med	2	5	2	3	0	2	2			2	2	1.6		RL 028	City Parks property	
29	Behind 9001 Chesshire	High	3	5	2	3	0	1	1		1	3	2	1.3	1	Collapse near path	RL 029	
30	W. TBHA Tennis Court	High	3	5	2	3	0	2	2		1	3	3	4.3	1	Severe undercut near path	RL 030	
31	Behind 8945 Dallas	Low	1	4	2	2	0	1	1			2	1	1		RL 031	City Parks property	
32	8710 Glacier (inside bay)	Low	2	2	2	0	0	2	2			3	1	1		RL 032		
33	8710 Glacier (lakeside)	High	2	6	3	3	0	2	2			4	2	1.3	1	Shoreline loss evident	RL 033	
34	Across from 8671 Glacier to across 14212 87th	Low	1	3	1	2	0	2	2			2	1	1		RL 034	City Parks property	
35	Across from 14170 87th	Low	1	3	1	2	0	2	2			2	2	2		RL 035	City Parks property	
36	Across from 14170 87th	Low	2	3	1	2	0	2	2			2	1	1		RL 036	City Parks property	
37	Behind from 8751 Dallas	Med	2	3	1	2	0	1	2		1	3	1	0.7		RL 037	City Parks property	
38	Behind 14123 87th	Med	2	3	1	2	0	2	2		1	3	1	1		RL 038	City Parks property	
39	Behind 14101 87th	Med	2	3	1	2	0	2	2		1	3	2	1.6		RL 039	City Parks property	
40	Behind 13912 85th PI	Low	1	3	1	2	0	2	2			2	1	1		RL 040	City Parks property	
41	Behind 8483 Rice Lk Rd	Med	1	3	1	2	0	2	2		1	2	1	1		RL 041	City Parks property	
42	Behind 8463 Rice Lk Rd	High	2	3	1	2	0	1	1		1	5	1	0.7	1	RL 042	City Parks property	
43	8628 Quarles	Low	1	3	0	0	3	1	1			7	1	0.7	1	RL 043		
44	TRPD S. Peninsula	Low	1	4	2	0	2	2	2			2	1	0.7		RL 044	Three Rivers property	
45	TRPD Culvert Entry	Med	2	6	3	1	2	2	2			2	1	1	Eroded by pipe inflow	RL 045	Three Rivers property	
46	Far W. corner of main lake	Low	1	4	1	3	0	1	1			2	1	1	1	RL 046	Three Rivers property	
47	Down hill from port-a-potty	High	3	4	1	3	0	1	1			3	2	1.6	3	100ft bank slumping/collapsing	RL 047	Three Rivers property
48	Behind 15641 91st Ave	Low	1	4	1	3	0	2	2			3	1	0.7		RL 048	City Parks property	
49	Behind 15599 91st Ave	High	3	4	1	3	0	1	1		1	3	1	0.7	1	Collapse near path	RL 049	City Parks property
50	Behind 15495-559 91st	Low	1	4	1	3	0	2	2			3	1	1		RL 050	City Parks property	
51	Behind 15395 91st Ave	High	3	4	1	3	0	2	2			4	2	1	2	Bank collapse 10ft wide	RL 051	City Parks property
52	Behind 15335 91st Ave	High	3	4	1	3	0	3	1	Y	1	5	0	0	3	Gabion failure - collapse	RL 052	City Parks property
53	Behind 15305 91st Ave	High	3	4	1	3	0	1	1	Y	1	7	2	1.6	2	Erosion @ end of gabion	RL 053	City Parks property
54	Behind 15155 91st Ave	Med	2	4	1	3	0	2	2		1	3	2	1.6	1	Small collapsed area	RL 054	City Parks property
55	Both 14749/14779 91st Ave	High	2	7	1	3	3	3	1	Y	1	7	2	2	2	Erosion around pipe inlet	RL 055	
56	Both 14629/14659 91st Ave	Med	2	4	1	3	0	2	2	Y		7	1	1	1	Steep upper bank eroding	RL 056	
57	Bay just W. of 14629 91st	Low	1	3	1	1	1	2	3			2	1	1		RL 057	City Parks property	
58	NW corner same bay	High	3	5	1	1	3	2	2			4	2	1.6	2	Major erosion around pipe	RL 058	City Parks property
59	N corner of same bay	Low	1	3	1	1	1	2	2			2	1	0.7	1	Minor areas of bank colla	RL 059	City Parks property
60	S length of same bay	Low	1	2	1	0	1	2	2			2	1	0.7		RL 060	City Parks property	
61	E. peninsula of same bay	High	3	6	2	3	1	2	2			4	3	2.3	1	Bank collapse	RL 061	City Parks property
62	14313 91st PI to E. peninsula	Med	2	5	2	3	0	2	3			4	1	1		RL 062	City Parks property	
63	50' E. Tristan Bay bridge	Med	2	5	3	0	2	2	2			2	2	2		RL 063	City Parks property	
64	Behind 14311/14341 92nd	High	2	3	3	0	0	2	3			3	2	1.3		High Exposure - boat wake	RL 064	City Parks property
65	Behind 14251 92nd to across 14100 92nd PI	Med	2	6	3	0	3	2	3			3	2	1.3	1	Areas of bank collapse	RL 065	City Parks property
66	Across 14060-90 92nd PI	High	1	6	3	0	3	2	3			2	1	1		High Exposure - boat wake	RL 066	City Parks property
67	N. side hairpin turn on creek	Low	1	6	3	0	3	2	2			3	2	1.3		RL 067	City Parks property	